

GRIPRAC, INC. PROGRESS LETTER REPORT

SCOPE OF WORK

EVALUATION AND TESTING OF NEW RAIL WITH SEVEN CLAMPS TO UL 2703

REPORT NO:

104502496LAX-001c

ISSUE DATE

27-May-2021

PAGES

3

DOCUMENT CONTROL NUMBER

GFT-OP-10a (6-March-2019) © 2019 INTERTEK





PROGRESS LETTER REPORT

25800 Commercentre Drive Lake Forest, CA 92630 USA

Telephone: (949) 448-4100 Facsimile: (949) 448-4111

www.intertek.com

Report No. 104502496LAX-001c Intertek Project No. G104502496

Ph: (310) 409-4616

Mustafa Erhan Yurttas Griprac, Inc. 633 S La Brea Ave Los Angeles, CA USA mustafa@griprac.com

Subject: Evaluation and Testing of New Rail with Seven (7) Clamps to UL 2703

Dear Mustafa,

27 May 2021

This letter report represents the progress of our evaluation of the above referenced product(s) to the requirements contained in the following standards:

Mounting Systems, Mounting Devices, Clamping/Retention Devices, and Ground Lugs for Use with Flat-Plate Photovoltaic Modules and Panels [UL 2703:2015 Ed.1]

SECTION 1

SUMMARY

This investigation was authorized by quote # Qu-01121659-0, dated 10/07/2020 and Qu-01162872-0, dated 04/06/2021. Intertek wishes to inform you that the evaluation is complete. Testing was completed and results listed in Section 2 below and the following non-conformances were identified.

SECTION 2

TESTING

The below listed table represents a summary and results of the tests which have been completed:

Completed Tests:

Assembly, Bonding Conductor (Part a), and Humidity Test (Pre and Post Bonding Path Resistance Tests)

Test Location: 25791 Commercentre Drive, Lake Forest, CA 92630

Bonding Conductor (Part b)
Test Location: Cedar Rapids, IA

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Version: 6-March-2017 Page 2 of 3 GFT-OP-10a



PROGRESS LETTER REPORT

Test Description	A l. l	Bonding Conductor Test		Humidity Test	
Clamp	Assembly	Part a	Part b	Bonding Path Pre HF10	Bonding Path Post HF10
Ironridge UFO mid clamps	Pass	Pass	Pass	Pass	Pass
Griprac universal grounding mid clamps/end clamps	Pass	Pass	Pass	Pass	Pass
Griprac grounding mid clamps	Pass	Pass	Pass	Pass	Pass
Unirac mid clamps	Pass	Pass	Pass	Pass	Pass
Unirac end clamp	Pass	Pass	Pass	Pass	Pass
SWH splice bars	Pass	Pass	Pass	Pass	Pass
Griprac grounding end clamps	Pass	Pass	Pass	Pass	Pass

SECTION 3

NON-CONFORMANCES/FINDINGS/DOCUMENT REQUIREMENT

- 1) Please provide LG module information to include in the listing report.
- 2) Please provide pertinent information about the system to be included in the listing report.
- 3) Please provide the most updated installation manual.
- 4) Please provide any change in applicant or manufacturer information through a client information sheet.

SECTION 4

PROJECT STATUS & ACTION

Issuance of this letter report is to provide an update on the testing and evaluation portion covered by Intertek Project No. G104502496.

If there are any questions regarding the results contained in this report, or any of the other services offered by Intertek, please do not hesitate to contact your dedicated Intertek Project Manager.

Completed by:	Deep Vora	Reviewed by:	Faraz Ebneali
Title:	Project Engineer	Title:	Reviewer
	, 0		
Signature:	(ex) ora	Signature	f. Ebnuli
Date	5/27/2021	Date:	5/27/2021
Date	3/2//2021	Date.	3/2//2021

Please note: this Letter Report does not represent authorization for the use of any Intertek certification marks.